

MAIN WEAVES

PLAIN WEAVE is the simplest and most common, with one thread of weft woven with one of warp.

la più semplice e la più diffusa, un filo di trama è intrecciato con un filo di ordito.

Characteristics:

- Excellent flatness
- Constant thickness
- Stable threads
- Little deformation

TWILL 2X2 with two threads of weft woven with two of warp.

Characteristics:

- Flesibility
- Easy to deform
- Reduced stability

SATIN 4H with one thread of weft passing over four of warp and vice versa.

Characteristics:

- Minimal thickness
- Smoother surface
- Greater flexibility
- Very easy to deform

